



North-West Elevation


Clay 'Spanish' tiles
Lime rendered rubble stone walls with limewash finish
Plinth of rubble stone




Front (North-East) Gable Elevation




South-East Elevation




Rear (South-West) Gable Elevation



Section A - A




Section B - B



Plan

Entrance access via timber ramp



North